

# COVANTA

Powering Today. Protecting Tomorrow.

## A Guided Facility Tour Checklist (Adult<sup>1</sup>)

### BEFORE YOU ARRIVE:

Please dress properly for your Covanta facility tour. On the day of your tour, please wear:

- Long sleeves (can be a shirt, blouse or a jacket)
- Long, ankle length pants and socks
- Flat heel shoes or work boot
- COVID mask may be required depending on plant and community restrictions



Do not wear the following on a tour: sandals, open toe, high-heel, or stiletto footwear. All visitors will be required to wear protective glasses, a hard hat and hearing protection provided by the facility.

**Note:** Although many areas on our tour route can be accessed using elevators, if you or someone in your party has special needs please call the facility in advance of your tour for further information.

### AFTER YOU ARRIVE:

After you arrive at one of our facilities, please make sure your tour guide provides the following safety gear and instruction before you begin your guided tour:

- Hard hat
- Protective glasses
- Reflective vest
- Ear protection
- Visitor tour video and safety briefing

You must be able to check ALL of the above boxes to begin your guided tour. Covanta facilities are industrial operations, and it is important to stay with your tour guide at all times. Never wander away on your own. Always be safe and enjoy your tour.

A COVID mask may be required depending on plant and community restrictions. Please do not come to the site if you have symptoms of COVID or are not feeling well.

<sup>1</sup>These are Covanta's requirements for tours on the tour route. Any deviation off tour route for longer than 30 minutes requires advanced personal protective equipment (PPE) and other requirements that should be discussed in advance with your Covanta contact.